

# GEOTECHNICAL DATA

## SUB-SURFACE INVESTIGATION AND REPORT:

- A.** Sub-surface investigation has been performed at the project site. This investigation was conducted, and a report obtained, solely for design purposes and is not a part of the Contract Documents.
- B.** The use and interpretation of this information will be entirely the responsibility of the using party. The Owner is not responsible for variations in the sub-surface conditions. Bidders shall decide for themselves the character of the material to be encountered.
- C.** The report of the findings for this investigation is on file in the Designer's office, and may be reviewed there by any prospective Bidder of Record. Bidders must coordinate review with Designer.

**END OF SECTION**