

Summary Sheet for Administration Building A

Administration Building A

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Front lot: Convert 1 existing accessible space to a van accessible space, add access aisles to all spaces without one. East lot: Add 2 car and 1 van space with access aisles. West lot: Add 2 car and 1 van space and access aisles for new and existing spaces.	Level 3	\$5,000.00
2	Add access aisles for existing accessible parking spaces as well as for the new accessible parking spaces.	Level 3	\$2,000.00
3	Add 8 car accessible parking signs and 3 van accessible signs.	Level 6	\$3,500.00
4	Evaluate and make necessary modifications to ensure all accessible parking spaces and access aisles have slopes no greater than 2% in all directions.	Level 3	\$12,000.00
5	Build curb ramps to serve each access aisle with a level landing. Ensure they do not project into the access aisle or cause a cross slope for the adjoining sidewalk.	Level 3	\$10,000.00
6	Alter or replace curb ramp as described above.	Level 3	\$3,000.00
7	Ensure all accessible parking spaces have a complaint path of travel to the sidewalks leading to the accessible entrance.	Level 3	\$6,500.00
8	Add directional signage at all non-accessible entrances.	Level 6	\$500.00
9	Install handrails on both sides of the sidewalk to create a ramp.	Level 3	\$4,800.00
10	Secure mats to the floor or ground to prevent slipping or curling. .	Level 5	\$200.00
11	Add directional signage at all inaccessible entrances.	Level 6	\$1,500.00
12	Remount fire extinguisher cabinet and first aid kits to a location outside of the circulation path or above something permanently fixed to the floor or wall. Ensure the highest operable part	Level 6	\$400.00
13	Lower the "Low" fountain on 2nd floor so the spout is at 36 inches above the finished floor.	Level 6	\$600.00
14	Install new, compliant signage on the wall next to the latch side of the door.	Level 6	\$500.00
15	Adjust the door closer. This should become a regular maintenance item.	Level 6	\$100.00
16	Secure mats to the floor or ground to prevent slipping or curling.	Level 8	\$200.00
17	Add tactile star on both jambs on the 1st floor.	Level 8	\$6,000.00
18	Add tactile star on both jambs on the 1st floor.	Level 6	\$400.00
19	Install compliant signage on the latch side of the door, between 48" and 60" from the floor and no more than 8" from the door jamb.	Level 6	\$1,600.00
20	Adjust the door closer. This should become a regular maintenance item.	Level 6	\$500.00
21	Lower the toilet paper dispensers so there is at least 1 1/2" between the toilet paper dispensers and the grab bars.	Level 11	\$1,200.00
22	Alter flush control mechanism so it's on the open side of the water closet.	Level 7	\$1,300.00
23	Modify toilet compartment or lavatories to provide a required maneuvering clearance.	Level 9	\$9,000.00

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
24	Install self-closing hinges at all accessible and ambulatory stalls so they self-close and ensure door pulls are provided on both sides of the stall door.	Level 7	\$2,000.00
25	It is unclear how deep the alcove is for the accessible urinal. If it is 24" deep or more the clear floor width is required to be a minimum of 36". If that is the case, adjustments need to be made to widen the alcove.	Level 7	\$3,600.00
26	Lower the mirror so it's no more than 40" to the bottom of the reflecting surface.	Level 11	\$800.00
27	Ensure all pipes, the supply line and any sharp areas are properly wrapped or protected from contact.	Level 5	\$1,000.00
28	Re-mount the rear grab bar for compliance.	Level 6	\$500.00
29	Raise the grab bar and re-mount the dispensers to 12" above the finished floor to the bottom of the devices so there is a 12" between the dispensers and the grab bar.	Level 9	\$700.00
30	Re-mount the toilet paper dispenser so that it's between 7" and 9" from the front of the water closet.	Level 9	\$800.00
31	Provide at least one of each type of vending machine with operation mechanisms no higher than 48" above the finished floor.	Level 10	\$4,000.00
32	Install new compliant sink.	Level 9	\$7,500.00

Grand Total	\$91,700.00
-------------	-------------

Summary Sheet for Field Office Building C

Field Office Building C

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Move one space over to the other side of the existing curb ramp and stripe an access aisle where 2 spaces can share the access aisle. Install a compliant curb ramp at the new access aisle.	Level 4	\$3,800.00
2	Raise existing signage and add "Van Accessible" sign in front of the van accessible space.	Level 4	\$500.00
3	Add one accessible parking space, which can share an access aisle with another space.	Level 4	\$1,200.00
4	Relocate existing sign to serve the new accessible parking space and mount it accordingly. Add one "Van Accessible" sign to the existing accessible parking space.	Level 6	\$250.00
5	Reconfigure landing to achieve a landing with slopes no greater than 2% in all directions.	Level 4	\$800.00
6	Install compliant curb ramps serving each access aisle. Two accessible space may share one access aisle.	Level 4	\$3,000.00
7	Adjust the closers for compliance. This should be a regular maintenance item.	Level 5	\$50.00
8	Properly secure mats to the ground or floor to prevent slipping or curling.	Level 9	\$150.00
9	Add directional signage indicating the location of the nearest accessible route.	Level 5	\$150.00
10	Install compliant signage on the latch side of the door.	Level 6	\$250.00
11	Install new hi/low compliant drinking fountain in a compliant location where it is not a protruding object.	Level 4	\$3,600.00
12	Permanently mount the signage on the latch side of the door.	Level 11	\$200.00
13	Adjust the door closer. This should become a regular maintenance item.	Level 11	\$100.00
14	Re-mount the hand sanitizer so the bottom is at 12" above the top of the side grab bar.	Level 11	\$100.00
15	Reinstall signage on the latch side of the door.	Level 11	\$200.00
16	Adjust the door closer. This should become a regular maintenance item.	Level 11	\$50.00
17	Wrap all pipes and sharp areas under the lavatory or otherwise protect from contact.	Level 11	\$50.00
18	Adjust water closet so it is 16"-18" from the side wall.	Level 11	\$600.00
19	Re-mount the hand sanitizer so the bottom is at 12" above the top of the side grab bar.	Level 11	\$50.00
20	Adjust stall doors to self-close and install pulls on the outside of the stall doors.	Level 11	\$200.00
21	Request new vending machines that have operable parts no higher than 48" above the finished floor.	Level 12	\$2,500.00
22	Break Rooms - Page 2	Level 7	\$3,250.00

Grand Total	\$21,050.00
-------------	-------------

Summary Sheet for Floating Maintenance Bldg. D

Floating Maintenance Bldg. D

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Add one accessible parking (van) space with an access aisle in the parking lot directly in front of the building entrance. Add a van accessible sign to serve the accessible parking space.	Level 2	\$1,500.00
2	Stripe a cross walk leading from the access aisle to the sidewalk. Ensure the slope of the path from the building to the parking has a running slope no greater than 5% and a cross slope on greater than 2%.	Level 3	\$500.00
3	Remove and replace curb ramp with a new curb ramp that has a running slope no greater than 8.33 % and a cross slope no greater than 2%.	Level 3	\$3,000.00
4	Adjust door closing mechanism. This should become a regular maintenance item.	Level 9	\$50.00
5	Properly secure each mat to the floor or ground to prevent slipping or curling.	Level 4	\$25.00
6	Add directional signage at each non-accessible entrance.	Level 5	\$100.00
7	Alter or replace the reception desk with a compliant section that is 36" high and 36" wide.	Level 11	\$1,000.00
8	Replace the existing unit with a new dual height unit that will serve as an accessible unit and a unit for standing persons. Ensure compliance with 602 Drinking Fountains. Provide a drinking fountain apron for the higher fountain.	Level 11	\$3,000.00
9	Adjust closing mechanisms.	Level 11	\$200.00
10	Lower the mirror so the bottom of the reflecting surface is 40" maximum above the finished floor.	Level 11	\$100.00
11	Provide protection at the exposed drains and water lines under the lavatory.	Level 11	\$200.00
12	Remount the rear grab bar so that it extends from the centerline of the water closet 12 inches minimum on one side and 24 inches minimum on the other side.	Level 11	\$150.00
13	Adjust stall door to self-close and install a door pull on the outside of the stall door.	Level 11	\$200.00
14	Alter or replace wall or partition to ensure the path of travel to the lavatory is a minimum of 36" clear width.	Level 11	\$3,500.00
15	Alter or replace wall or partition to ensure the path of travel to the lavatory is a minimum of 36" clear width.	Level 11	\$0.00
16	Lower the mirror so the bottom of the reflecting surface is 40" maximum above the finished floor.	Level 11	\$100.00
17	Remount the hand sanitizer so there is a 12" between it and the side grab bar.	Level 11	\$125.00
18	Remount the rear grab bar so that it extends from the centerline of the water closet 12 inches minimum on one side and 24 inches minimum on the other side.	Level 11	\$150.00

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
19	Replace flush valve on the open/approach side of the water closet or replace unit for compliance.	Level 11	\$1,750.00
20	Adjust stall door to self-close and install pull on the outside of the stall door.	Level 11	\$200.00

Grand Total	\$15,850.00
-------------	-------------

Summary Sheet for Garage Building E

Garage Building E

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Add one accessible parking (van) space with an access aisle in the parking lot directly in front of the building entrance. Add a van accessible sign to serve the accessible parking space.	Level 2	\$1,500.00
2	Stripe a cross walk leading from the access aisle to the accessible entrance. Ensure the slope of the path from the building to the parking has a running slope no greater than 5% and a cross slope no greater than 2%.	Level 3	\$650.00
3	Modify sidewalk to ensure running slope is 5% or less and cross slope no greater than 2%, otherwise install edge protection and handrails with level landing areas at the top and bottom of the ramp which do not exceed 2% slope in any direction.	Level 4	\$5,000.00
4	Adjust door closing mechanism. This should become a regular maintenance item.	Level 11	\$100.00
5	Properly secure each mat to the floor or ground to prevent slipping or curling.	Level 11	\$100.00
6	Install directional signage to at inaccessible entrances to the accessible entrance, and signage at the accessible entrance.	Level 6	\$250.00
7	Alter or replace the reception desk with a compliant section that is 36" high and 36" wide.	Level 11	\$2,800.00
8	Replace the existing unit with a new dual height unit that will serve as an accessible unit and a unit for standing persons. Ensure compliance with 602 Drinking Fountains. Provide a drinking fountain apron for the higher fountain.	Level 11	\$3,000.00
9	Reverse the swing of the door or install an automatic door opening device.	Level 11	\$1,870.00
10	Modify lavatory to provide 34" maximum height to the rim of the lavatory.	Level 11	\$850.00
11	Lower mirror so bottom of the reflecting surface is no higher than 40" above finished floor.	Level 11	\$100.00
12	Provide protection at the exposed water lines under the lavatory.	Level 11	\$200.00
13	Lower paper towel dispenser with the controls no higher than 48" above finish floor.	Level 11	\$100.00
14	Reposition water closet to achieve compliance. Replace toilet seat to achieve 17" 19" height.	Level 11	\$1,200.00
15	Replace flush valve on the open/approach side of the water closet or replace unit for compliance.	Level 11	\$1,750.00
16	Install compliant grab bars.	Level 11	\$750.00
17	Install compliant signage on the wall within 8" of the latch side of the door, between 48" and 60" from the finished floor.	Level 11	\$250.00
18	Reverse the swing of the door or install an automatic door opening device.	Level 11	\$1,870.00
19	Lower mirror so bottom of the reflecting surface is no higher than 40" above finished floor.	Level 11	\$100.00

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
20	Modify lavatory to provide 34" maximum height to the rim of the lavatory.	Level 11	\$850.00
21	Provide protection at the exposed valve under the lavatory.	Level 11	\$200.00
22	Replace with lever style faucet controls.	Level 11	\$500.00
23	Reposition water closet to achieve compliance. Replace toilet seat to achieve 17" 19" height.	Level 11	\$1,200.00
24	Install compliant grab bars	Level 11	\$750.00
25	Lower paper towel dispenser towel dispenser with the controls no higher than 48" above finish floor.	Level 11	\$100.00
26	Modify sink to provide 34" maximum height.	Level 11	\$3,600.00
27	Modify counter to provide the required toe and knee clearance. Cost for this is included in violation #27.	Level 11	\$0.00
28	Lower a portion of the counter so it is no higher than 34" above the finished floor. Add an accessible table.	Level 11	\$1,100.00

Grand Total	\$30,740.00
-------------	-------------

Summary Sheet for Highway Marking Building F

Highway Marking Building F

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Add one accessible parking space that is van accessible with an access aisle across with compliant van accessible signage.	Level 2	\$3,000.00
2	Stripe a cross walk leading from the access aisle to the sidewalk. Ensure the slope of the path from the building to the parking has a running slope no greater than 5% and a cross slope on greater than 2%.	Level 3	\$500.00
3	Remove and replace curb ramp to achieve a 8% running slope and a 2% cross slope with flared sides that have slopes no greater than 10%. Ensure the curb ramp has a level landing at the top.	Level 4	\$1,800.00
4	Adjust door closing mechanisms. This should become a regular maintenance item.	Level 11	\$100.00
5	Properly secure each mat to the floor or ground to prevent slipping or curling.	Level 11	\$100.00
6	Install signage at all non-accessible entrances indicating the location of the nearest accessible entrance.	Level 11	\$250.00
7	Replace the existing unit with a new dual height unit that will serve as an accessible unit and a unit for standing persons. Ensure compliance with 602 Drinking Fountains. Provide a drinking fountain apron for the higher fountain.	Level 11	\$3,000.00
8	Alter or replace the reception desk with a compliant section that is 36" high and 36" wide.	Level 11	\$2,200.00
9	Remount signage for both the Men's and Women's restrooms on wall at the latch	Level 11	\$100.00
10	Adjust door closing mechanisms. This should become a regular maintenance item.	Level 11	\$100.00
11	Relocate the mirror to 40" maximum above the floor to the bottom of the reflective surface.	Level 11	\$100.00
12	Provide protection at the exposed valve and water lines under the lavatory.	Level 11	\$250.00
13	Remount the rear grab bar so that it extends from the centerline of the water closet 12 inches minimum on one side and 24 inches minimum on the other side.	Level 11	\$650.00
14	Replace flush valve on the open/approach side of the water closet or replace unit for compliance.	Level 11	\$1,750.00
15	Adjust toilet compartment door to self close. Add a door pull to the both sides of the compartment door.	Level 11	\$200.00
16	Adjust door closing mechanisms. This should become a regular maintenance item.	Level 11	\$100.00
17	Lower mirror so bottom of the reflecting surface is no higher then 40" above finished floor.	Level 11	\$100.00
18	Provide protection at the exposed valve and water lines under the lavatory.	Level 11	\$100.00

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
19	Re-mount the dispenser at least 12" above the top of the gripping surface of the side grab bar.	Level 11	\$250.00
20	Remount the rear grab bar so that it extends from the centerline of the water closet 12 inches minimum on one side and 24 inches minimum on the other side.	Level 11	\$150.00
21	Adjust toilet compartment door to self close. Add a door pull to the inside of the compartment door.	Level 11	\$200.00
22	Re-arrange breakroom to ensure a clear 36" wide path and a clear 60" turning radius are provided.	Level 11	\$100.00
23	Re-arrange breakroom to ensure a clear 36" wide path and a clear 60" turning radius are provided. Cost is included under violation #22.	Level 11	\$0.00
24	Relocate the refrigerators to allow for the required maneuvering clearance. Cost is included under violation #22.	Level 11	\$0.00
25	Modify sink to provide 34" maximum height.	Level 11	\$3,250.00
26	Modify counter to provide the required toe and knee clearance. Cost for this is included in violation #25.	Level 11	\$0.00
27	Provide a microwave that is within the required reach ranges.	Level 11	\$350.00

Grand Total	\$18,700.00
-------------	-------------

Summary Sheet for Construction Building H

Construction Building H

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Add 2 accessible parking spaces (1 van accessible), a shared access aisle and accessible signage so it best serves the building entrance.	Level 2	\$3,000.00
2	Install 2 Accessible parking spaces for each parking lot with access aisles and compliant signage.	Level 2	\$4,000.00
3	Remove and replace curb ramp to achieve compliant slopes.	Level 3	\$3,000.00
4	Properly secure all floor mats to prevent slipping or curling.	Level 11	\$100.00
5	Add directional signage.	Level 11	\$150.00
6	Move furniture to allow for the required 36" wide path of travel.	Level 11	\$100.00
7	Replace the existing unit with a new dual height unit that will serve as an accessible unit and a unit for standing persons. Ensure compliance with 602 Drinking Fountains. Provide a drinking fountain apron for the higher fountain.	Level 11	\$3,000.00
8	Replace the existing unit with a new dual height unit that will serve as an accessible unit and a unit for standing persons. Ensure compliance with 602 Drinking Fountains. Provide a drinking fountain apron for the higher fountain.	Level 11	\$3,000.00
9	Remount all signage to the wall at the latch side of the door, between 48" and	Level 11	\$400.00
10	Reverse the swing of the doors or install automatic door openers.	Level 11	\$1,870.00
11	Add directional signage directing people to the nearest accessible restrooms.	Level 11	\$300.00
12	Relocate the mirror to 40" maximum above the floor to the bottom of the reflective surface.	Level 11	\$200.00
13	Modify lavatories to provide 34" maximum height to the rim.	Level 11	\$4,000.00
14	Provide protection at the exposed valve under the lavatory.	Level 11	\$200.00
15	Replace with lever style faucet controls.	Level 11	\$1,000.00
16	Reposition water closets so they are 16"-18" from the side wall.	Level 11	\$2,000.00
17	Replace toilet seat to achieve 17"-19" height.	Level 11	\$400.00
18	Provide a 36" long rear grab bar that it extends from the centerline of the water closet 12 inches minimum on one side and 24 inches minimum on the other side.	Level 11	\$750.00
19	Lower paper towel dispensers so the controls are no higher than 48" above finish floor.	Level 11	\$200.00
20	Relocate the lockers or install an automatic door opener.	Level 11	\$1,870.00
21	Adjust closing mechanisms.	Level 11	\$100.00
22	Provide a 36" long rear grab bar that it extends from the centerline of the water closet 12 inches minimum on one side and 24 inches minimum on the other side.	Level 11	\$750.00
23	Relocate the mirror to 40" maximum above the floor to the bottom of the reflective surface.	Level 11	\$200.00
24	Provide protection at the exposed valve under the lavatory.	Level 11	\$100.00

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
25	Modify lavatory to provide 34" maximum height to the rim.	Level 11	\$2,000.00
26	Remove stall partitions. For the Women's room, the water closet would need to be relocated next to the wall.	Level 11	\$2,500.00
27	Replace flush valve on the open/approach side of the water closet or replace unit for compliance. This can be resolved when the room is altered as noted above.	Level 11	\$1,750.00
28	This should be resolved when the restroom is altered.	Level 11	\$650.00
29	Provide a compliant sink in a location where the required clear floor space is provided.	Level 11	\$2,000.00
30	Request vending machines that have operable parts that are no higher than 48" above finished floor.	Level 12	\$0.00

Grand Total	\$39,590.00
-------------	-------------

Summary Sheet for Region 1 Transportation Management Center

Transportation Management Center

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Relocate the 2 accessible parking spaces (one being van accessible), a shared access aisle and compliant signage in front of the building's main entrance.	Level 2	\$3,500.00
2	Add accessible signage, with one designating the space as "Van Accessible".	Level 5	\$500.00
3	Stripe a cross walk leading from the remote parking lot to the building sidewalk.	Level 11	\$500.00
4	Properly secure each mat to the floor or ground to prevent slipping or curling.	Level 11	\$100.00
5	Adjust closing mechanism.	Level 11	\$150.00
6	Alter or replace the reception desk with a compliant section that is 36" high and 36" wide.	Level 11	\$2,500.00
7	Re-mount fountain so the leading edge is no higher than 27" above finished floor..	Level 11	\$250.00
8	Re-mount fountain so the leading edge is no higher than 27" above finished floor.	Level 11	\$250.00
9	When door is altered for compliance, see below, sign will need to be adjusted.	Level 11	\$200.00
10	Reverse the swing of the door or install a power door opener.	Level 11	\$2,750.00
11	Re-mount the water closet to achieve 16" - 18" from the side wall.	Level 11	\$1,750.00
12	Replace flush valves to the open/approach side of the water closet or replace unit for compliance.	Level 11	\$3,500.00
13	Re-mount toilet paper dispensers so they are between 7"-9" to the center of the dispenser from the front of the water closets.	Level 11	\$600.00
14	Install door pulls on the inside of all accessible stalls, adjust the Men's stall door mechanism to self-close and replace the lock on the Women's stall door with one that does not require grasping and twisting to operate.	Level 11	\$750.00
15	Add a second coat hook that is no higher than 48" above finished floor.	Level 11	\$600.00
16	Adjust door closing mechanisms. This should become a regular maintenance item.	Level 11	\$300.00
17	Modify the partition to achieve the required toe clearance.	Level 11	\$250.00
18	Modify sink to provide 34" maximum height.	Level 11	\$2,000.00
19	Modify counter to provide the required toe and knee clearance. Cost for this is included in violation #18.	Level 11	\$0.00
20	Relocate the table to allow for the required clear floor space.	Level 12	\$100.00

Grand Total	\$20,550.00
-------------	-------------

Summary Sheet for Materials & Tests Building B

Materials & Tests Building B

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Make modifications to widen the accessible parking space to meet the minimum requirements for a "Van Accessible" parking space.	Level 3	\$1,500.00
2	Evaluate and make necessary modifications to ensure the accessible parking space and access aisle has slopes no greater than 2% in all directions. A reasonable tolerance, published by the US Access Board, allow up to .05%. These are slightly over that so they are given a lower priority but should be watched.	Level 9	\$3,000.00
3	Add "Van Accessible" parking signage. (Price included in Violation #1)	Level 3	\$250.00
4	Remove and replace curb ramp to achieve a 8% running slope and a 2% cross slope with flared sides that have slopes no greater than 10%. Ensure the curb ramp does not protrude into the access aisle.	Level 3	\$3,800.00
5	Adjust the door closer. This should be a regular maintenance item.	Level 6	\$50.00
6	Properly secure mats to the ground or floor to prevent slipping or curling.	Level 6	\$200.00
7	Add directional signage at all non-accessible entrances.	Level 6	\$500.00
8	Install new hi/low compliant drinking fountain in a compliant location.	Level 6	\$3,600.00
9	Adjust the door closer to less than 5 lbs. of pressure. This should be a regular	Level 8	\$100.00
10	Lower the mirror so that the bottom of the reflecting surface does not	Level 8	\$200.00
11	Lower lavatory.	Level 7	\$300.00
12	Insulate or otherwise protect the pipes and supply lines from contact.	Level 7	\$250.00
13	Relocate the water closet so it's centerline is between 16" and 18 from the side wall or install an ofset flange.	Level 7	\$650.00
14	Raise the hand sanitizer to at least 12" above the grab bar.	Level 7	\$150.00
15	Re-mount the rear grab bar so it's in compliance with this section.	Level 6	\$150.00
16	Modify toilet compartment to provide a required maneuvering clearance/	Level 7	\$3,500.00
17	Install self-closing hinges stall door to self-close and install pull handle on both sides of the stall door.	Level 7	\$750.00
18	Because the alcove is deeper than 24" the width is required to be 36". That partition will need to be moved to accommodate the 36" requirement and it will help resolve the requirement between the partition and the water closet as well.	Level 7	\$1,200.00
19	Lower the urinal so the rim is at or below 17" above finished floor.	Level 7	\$650.00
20	Move flush valve to the approach side.	Level 7	\$850.00
21	Replace casework with counter to ensure rim of sink or counter surface is 34 inches maximum above finished floor.	Level 7	\$3,250.00

Grand Total	\$24,900.00
-------------	-------------

Summary Sheet for District 17 Office Johnson City

District 17 Office Johnson City

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Each lot is required to have at least ONE accessible parking space unless all accessible spaces are moved closer to the building. If that's the case, the lot across the street is required to have signage indicating the location the accessible parking space was moved to. This is called 'equivalent facilitation' in the standards. If the two spaces are moved side by side, one of the accessible parking space needs to be van accessible with 11' wide space and 5' wide access aisle or 96" wide space and 96" wide access aisle. They can share the access aisle. Stripe both spaces and the access aisle and provide required accessible parking signage in front of both spaces and an additional 'van' sign in front of at least one of them.	Level 4	\$500.00
2	Accessible parking spaces and aisle need to be re-graded, resurfaced or moved to a more level location so the slope is no more than 2% in all directions.	Level 4	\$8,000.00
3	Since the existing accessible parking space does not comply, the new accessible parking spaces and access aisle should be relocated so they are as close as possible to the main entrance to the building.	Level 4	\$3,500.00
4	Install compliant signage for each accessible space and an additional "van" sign in front of one of them.	Level 9	\$250.00
5	Remove and replace sidewalk areas to achieve a 5% maximum running slope or install handrails, edge protection and landing areas making the path of travel compliant with the ramp standards.	Level 3	\$2,800.00
6	Install wheel-stops in front of all parking spaces adjacent to the accessible route to protect the width of the accessible route. They should be 2 1/2' back from the sidewalk to account for vehicle hangover.	Level 3	\$1,500.00
7	Because of the size and function of the second floor, there is no need to install vertical access. However, to ensure program access, there must be an alternative location for conferences and meetings that is on an accessible route.	Level 4	\$1,750.00
8	Adjust the door closer mechanism. This should become a regular maintenance item.	Level 6	\$100.00
9	Where signage is provided, install compliant signage on the wall on the latch	Level 6	\$500.00
10	Remove cabinets that are blocking the maneuvering clearance or install an automatic door opening device.	Level 5	\$1,850.00
11	Remove cabinets to provide the required maneuvering clearances.	Level 4	\$150.00
12	Remove cabinets to provide the required maneuvering clearances.	Level 4	\$50.00
13	Remove cabinets to provide the required maneuvering clearances.	Level 10	\$50.00
14	Provide protection under the lavatory.	Level 5	\$150.00
15	Re-mount mirror so the bottom of the reflective surface (not the frame) is at or below 40".	Level 8	\$100.00

16	Install compliant signage on the wall on the latch side of the door, between 48" and 60", no more than 8" from the door frame.	Level 6	\$100.00
#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
17	Re-arrange furniture so the required clear floor space is provided for the room and for each element offered within the room.	Level 12	\$200.00
18	Replace the sink with a compliant unit that provides the required clear floor space and knee/toe clearances for a frontal approach and is no more than 34" high.	Level 6	\$3,250.00

Grand Total	\$24,800.00
-------------	-------------

Summary Sheet for District 17-Office Morristown

District 17-Office Morristown

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Since the existing parking space is 13' wide, it can serve as the van accessible space with proper signage. A second accessible parking space that is 8' wide needs to be added. Ensure both spaces have slopes no greater than 2% in all directions.	Level 4	\$500.00
2	Restripe parking space directly left of the van accessible space as the access aisle so that it is located between the van space and the new accessible space. Ensure slopes are no greater than 2% in all directions.	Level 4	\$500.00
3	A "Van Accessible" sign needs to be added and a new accessible sign needs to be added for the new parking space.	Level 9	\$25.00
4	Install a compliant sidewalk leading from the access aisle across the grass to the existing sidewalk.	Level 3	\$6,000.00
5	Install compliant barrier along the entire length of the ramp on both sides.	Level 3	\$1,800.00
6	Remove the existing curb ramp to provide the fully compliant path of travel noted above.	Level 4	\$1,500.00
7	Alter or replace the landing to ensure it is 60" long. An alternate solution would be to provide a power door mechanism to the door at the top of the ramp.	Level 11	\$2,750.00
8	Because of the size and function of the second floor, there is no need to install vertical access. However, to ensure program access, there must be an alternative location for conferences and meetings that is on an accessible route.	Level 4	\$1,750.00
9	Secure the mats in front of the main entry door to avoid slipping or curling.	Level 11	\$100.00
10	Adjust the door closer mechanism. This should become a regular maintenance item.	Level 6	\$100.00
11	Adjust the door closer mechanism. This should become a regular maintenance item.	Level 6	\$100.00
12	Relocate the metal shelving and filing cabinets that are blocking the maneuvering clearance and reducing the clear width in the hallway.	Level 6	\$200.00
13	Install compliant signage on the wall on the latch side of the door, between 48" and 60", no more than 8" from the door frame.	Level 6	\$250.00
14	Adjust the door closer mechanism. This should become a regular maintenance item.	Level 6	\$100.00
15	Relocate flush valve so it is on the open side of the water closet.	Level 6	\$650.00
16	Reinstall both grab bars so they are at compliant height and locations.	Level 10	\$250.00
17	Ensure the valves under the lavatory are properly protected against contact. Make sure there are not rough or abrasive surfaces.	Level 5	\$250.00
18	Lower the mirrors to 40" maximum above the floor to the bottom of the reflective surface.	Level 10	\$100.00
19	Install compliant soap dispenser no higher than 48" above the finished floor to the operable part.	Level 6	\$50.00
20	Relocate grab bar so it is no more than 12" from the rear wall.	Level 10	\$50.00

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
21	Relocate the shelving so it is not in the clear floor space of any of the required elements.	Level 10	\$150.00
22	Re-arrange furniture so the required clear floor space is provided for the room and for each element offered within the room.	Level 12	\$200.00
23	Replace the sink with a compliant unit that provides the required clear floor space and knee/toe clearances for a frontal approach and is no more than 34" high.	Level 6	\$2,750.00
24	Replace table with one that provides the 27" required knee clearance.	Level 10	\$600.00

Grand Total	\$20,725.00
-------------	-------------

Summary Sheet for District 18 Office Newport

District 18 Office Newport

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Restripe the existing parking to provide for three accessible spaces, each with an access aisle serving it. Two spaces can share one access aisle.	Level 4	\$600.00
2	When the lot is restriped, as noted above, ensure there is a crosswalk that connects the access aisles of all of the accessible spaces to the path leading to the front entry.	Level 4	\$800.00
3	Raise signage so the bottom most character is 60" minimum from the ground. Once the parking is restriped, two additional signs will be needed and one "van accessible" sign will also be required.	Level 4	\$550.00
4	Alter the transition between the parking surface and the sidewalk leading to the building to ensure the path of travel is as smooth as possible and the slopes are compliant.	Level 2	\$3,000.00
5	Alter or replace the landing to ensure it is 60" long. An alternate solution would be to provide a power door mechanism to the door at the top of the ramp.	Level 11	\$2,750.00
6	Because of the size and function of the second floor, there is no need to install vertical access. However, to ensure program access, there must be an alternative location for conferences and meetings that is on an accessible route.	Level 4	\$1,750.00
7	Adjust the door closer mechanism. This should become a regular maintenance item.	Level 4	\$100.00
8	Replace the existing unit with a new dual height unit that will serve as an accessible unit and a unit for people standing or install a standard height unit in an alternate location. Ensure compliance with 602 Drinking Fountains. If not recessed, provide an apron for the higher fountain to bring it's leading edge to 27" if necessary. Other option: Remove drinking fountains entirely.	Level 5	\$3,840.00
9	Remove metal shelving and filing cabinets that are blocking the maneuvering	Level 8	\$100.00
10	Install compliant signage on the wall on the latch side of the door, between 48" and 60", no more than 8" from the door frame.	Level 8	\$100.00
11	Adjust the door closer mechanism. This should become a regular maintenance item.	Level 8	\$50.00
12	Adjust the door closer mechanism. This should become a regular maintenance item.	Level 8	\$50.00
13	Install the proper protection for the drain pipes and water valves under the lavatory.	Level 8	\$250.00
14	Lower the mirrors to 40" maximum above the floor to the bottom of the reflective surface.	Level 8	\$100.00
15	Relocate the soap dispenser to an accessible location and height where it doesn't obstruct the use of the grab bar.	Level 8	\$100.00
16	Reinstall both grab bars so they are at compliant height and locations.	Level 8	\$50.00

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
17	The Men's restroom needs to be gutted and fully renovated for compliance. This can be delayed until there is an employee with a disability who needs full access to the Men's restroom. However, an interim solution (which is what costs reflect) would be to make BOTH restrooms unisex restrooms, one in the garage and one in the office area.	Level 11	\$750.00
18	Re-arrange furniture so the required clear floor space is provided for the room and for each element offered within the room.	Level 12	\$100.00
19	Replace the sink with a compliant unit that provides the required clear floor space and knee/toe clearances for a frontal approach and is no more than 34" high.	Level 12	\$3,250.00
20	Replace table with one that provides the required knee clearance.	Level 12	\$600.00

Grand Total	\$18,890.00
-------------	-------------

Summary Sheet for District 19 Office Harriman

District 19 Office Harriman

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Relocate this accessible parking spaces to the end of the sidewalk that leads to the main entry on the southwest side of the buiding. Two accessible spaces are required and both should be where the access aisle can line up with the sidewalk and provide a compliant path of travel to the building entrance. Both spaces can share the access aisle.	Level 2	\$3,500.00
2	Two new signs should be provided at the accessible spaces once they are created. Signs must be in front of each space and should be no less than 60" high to the bottom most character.	Level 9	\$50.00
3	Either install a compliant path of travel from the existing front accessible space to the ramp that leads sidewalk or move the accessible parking to the southwest lot near the end of the sidewalk that does lead to the ramp to the entrance.	Level 3	\$7,500.00
4	Alter or replace the sidewalk so that it is smooth and has a running slope no greater than 5% and a cross slope no greater than 2%. With the surface improved, it could be treated like a ramp with the installation of handrails on both sides and level landing areas in compliance with the standards. Another option would be to run an accessible route along the front of the building, by the ramp, and connecting the two paths on the south side.	Level 2	\$8,200.00
5	Alter or replace the ramp to achieve a running lope no greater than 8.33% and a landing that doesn't exceed 2% in any direction.	Level 8	\$6,000.00
6	Alter or replace the landing to ensure it is 60" long and ensure the slope does not exceed 8.3%. A power assisted door may help with the landing issue but will not help with the ramp slope, so alteration is the only road to compliance.	Level 8	\$10,000.00
7	Because of the size and function of the second floor, there is no need to install vertical access. However, to ensure program access, there must be an alternative location for conferences and meetings that is on an accessible route.	Level 12	\$750.00
8	Adjust the door closer mechanism. This should become a regular maintenance item.	Level 4	\$100.00
9	Secure the mat in front of the main entry door to avoid slipping or curling.	Level 11	\$100.00
10	Relocate these items to a location that is not along the circulation path of travel.	Level 8	\$50.00
11	Replace the existing unit in a compliant location, with a new dual height unit that will serve as an accessible unit and a unit for standing persons. Ensure compliance with 602 Drinking Fountains. Provide an apron for the fountain to bring it's leading edge to 27" Other options: Install a single unit at standard height in another location or remove drinking fountains entirely.	Level 8	\$3,250.00

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
12	Adjust the door closer mechanism. This should become a regular maintenance item.	Level 8	\$50.00
13	Reverse the door swing or install a power door mechanism for compliance.	Level 6	\$2,750.00
14	Install compliant signage on the wall on the latch side of the door, between 48" and 60", no more than 8" from the door frame.	Level 6	\$250.00
15	Reinstall the side grab bars so it meets the compliant height and location requirements.	Level 11	\$150.00
16	Remount the toilet paper dispenser so it is 7" to 9" to the center of the two rolls, from the front of the water closet.	Level 11	\$100.00
17	The Men's restroom needs to be gutted and fully renovated for compliance. This can be delayed until there is an employee with a disability who needs full access to the Men's restroom. However, an interim solution (which is what costs reflect) would be to make BOTH restrooms unisex restrooms, one in the garage and one in the office area.	Level 8	\$750.00
18	Re-arrange furniture so the required clear floor space is provided for the room and for each element offered within the room.	Level 10	\$50.00
19	Replace the sink with a compliant unit that provides the required clear floor space and knee/toe clearances for a frontal approach and is no more than 34" high.	Level 10	\$1,000.00
20	Replace table with one that provides the 27" required knee clearance.	Level 10	\$400.00
21	Adjust the door closer mechanism. This should become a regular maintenance item.	Level 10	\$25.00

Grand Total	\$45,025.00
-------------	-------------

Summary Sheet for District 19 Office LaFollette

District 19 Office LaFollette

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Provide at least one additional accessible parking space (total of two). One of which must be van accessible with 11' wide space and 5' wide access aisle or 96" wide space and 96" wide access aisle. Stripe access aisle and provide required accessible van parking signage.	Level 4	\$3,000.00
2	Add compliant access aisle (with slopes no greater than 2% in all directions) between the two accessible parking spaces.	Level 2	\$350.00
3	Raise sign and relocate so it is not blocked by landscape. An additional accessible parking sign with "Van Accessible" needs to be installed at the new Van Accessible parking space.	Level 6	\$350.00
4	Entities are required to 'maintain' accessible routes in an accessible condition. Ensure all landscape debris is cleaned off the accessible route. It is recommended that the	Level 4	\$50.00
5	Remove and replace curb ramp and top landing to achieve a complaint curb ramp with 1:48 maximum cross slope while maintaining the required 1:20 maximum running slope.	Level 11	\$500.00
6	Remove and replace bottom of ramp landing to achieve a 1:48 maximum cross slope.	Level 11	\$1,500.00
7	A barrier edge protection needs to be added on both sides of the ramp.	Level 5	\$1,000.00
8	Alter or replace the landing to ensure the landing is 60" long and ensure the slope of the ramp itself does not exceed 8.3%. A power assisted door may an alternative to ensure access into the building.	Level 7	\$1,130.00
9	Because of the size and function of the second floor, there is no need to install vertical access. However, to ensure program access, there must be an alternative location for conferences and meetings that is on an accessible route.	Level 12	\$1,750.00
10	Secure the mat in front of the main entry door to avoid slipping or curling.	Level 11	\$100.00
11	Adjust the door closer mechanism. This should become a regular maintenance item.	Level 5	\$25.00
12	Secure the interior mats throughout the facility to avoid slipping or curling.	Level 5	\$50.00
13	Remove metal shelving and filing cabinets that are blocking the maneuvering clearance or install an automatic door opening device.	Level 7	\$50.00
14	Install compliant signage on the wall on the latch side of the door, between 48" and 60", no more than 8" from the door frame.	Level 7	\$250.00
15	Adjust the door closer mechanism. This should become a regular maintenance item.	Level 7	\$50.00
16	Relocate water closet so that it is mounted between 16"-18" off the side wall.	Level 9	\$2,045.00
17	Relocate grab bar to meet the requirements noted above.	Level 11	\$414.00
18	Re-arrange furniture so the required clear floor space is provided for the room and for each element offered within the room.	Level 10	\$50.00

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
19	Replace the sink with a compliant unit that provides the required clear floor space and knee/toe clearances for a frontal approach and is no more than 34" high.	Level 10	\$2,820.00
20	Replace table with one that provides the required knee clearance.	Level 10	\$400.00

Grand Total	\$15,884.00
-------------	-------------

Summary Sheet for District 17 Elizabethton Maint. Office

District 17 Elizabethton Maint. Office

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	When striping the lot, ensure the van accessible space and access aisle are in compliance.	Level 5	\$600.00
2	Regrade the access aisle prior to striping to achieve a running slope and a cross slope no greater than 2%.	Level 4	\$3,200.00
3	Install new van accessible signage.	Level 5	\$250.00
4	Remove and replace paving at the entrance to achieve slopes in all directions no greater than 1:48.	Level 3	\$3,000.00
5	Replace all cylindrical door handles with lever style door hardware.	Level 5	\$375.00
6	Alther the door and/or threshold to achieve a 1/2" high maximum threshold.	Level 3	\$1,500.00
7	Replace the existing unit with a new dual height unit that will serve as an accessible unit and a unit for standing persons. Ensure compliance with 602 Drinking Fountains. Provide a drinking fountain apron for the higher fountain.	Level 10	\$3,000.00
8	Relocate the items that are blocking the required 18" maneuvering clearance on the pull side.	Level 3	\$200.00
9	Adjust door closer mechanism. This should become a regular maintenance item.	Level 6	\$50.00
10	Install compliant signage on the wall within 8" of the latch side of the door, between 48" and 60" from the finished floor.	Level 6	\$250.00
11	Replace flush valve on the open/approach side of the water closet or replace unit for compliance.	Level 6	\$1,750.00
12	Lower the paper towel dispensers so the highest operable part is no higher than 48" above the finished floor in both the Men's and Women's restrooms.	Level 9	\$50.00
13	Relocate the items that are blocking the required 18" maneuvering clearance on the pull side.	Level 6	\$50.00
14	Install compliant signage on the wall within 8" of the latch side of the door, between 48" and 60" from the finished floor.	Level 6	\$250.00
15	Lower mirror to 40" maximum above the floor to the bottom of the reflective surface.	Level 10	\$100.00
16	The water closets will need to be relocated to achieve the 16"-18" centerline dimension or an offset flange installed.	Level 9	\$1,000.00
17	Relocate rear grab bars according to 604.5.2. If they are moved so they are 6" from the side wall, they will comply.	Level 11	\$200.00
18	Lower the paper towel dispensers so the highest operable part is no higher than 48" above the finished floor in both the Men's and Women's restrooms.	Level 9	\$100.00
19	Secure lavatory to wall and remove wood plank.	Level 6	\$350.00
20	Provide an accessible picnic table.	Level 11	\$1,900.00

Grand Total	\$18,175.00
-------------	-------------

Summary Sheet for District 18 Field Office Newport

District 18 Field Office Newport

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Install new van accessible signage.	Level 9	\$250.00
2	Re-grade both access asiles so they have slopes no greater than 1:48 in all directions in its entirety.	Level 2	\$3,500.00
3	Properly secure each mat to the floor or ground to prevent slipping or curling.	Level 7	\$50.00
4	Replace the existing unit with a new dual height unit that will serve as an accessible unit and a unit for standing persons. Ensure compliance with 602 Drinking Fountains. Provide a drinking fountain apron for the higher fountain.	Level 10	\$3,000.00
5	Replace table with one that provides the required 27" knee clearance.	Level 4	\$800.00
6	Properly secure mats to the floor or ground to keep them from slipping	Level 7	\$50.00
7	Install compliant signage on the wall within 8" of the latch side of the door, between 48" and 60" from the finished floor.	Level 6	\$250.00
8	Adjust door closing mechanism. This should become a regular maintenance item.	Level 9	\$100.00
9	Relocate the mirrors to 40" maximum above the floor to the bottom of the reflective surface.	Level 10	\$100.00
10	Lower the hand sanitizer so the operable part is no higher than 48" above finished floor.	Level 9	\$100.00
11	Install compliant signage on the wall within 8" of the latch side of the door, between 48" and 60" from the finished floor.	Level 6	\$250.00
12	Relocate the items that are blocking the required maneuvering clearance on the pull side.	Level 6	\$100.00
13	Adjust door closing mechanism. This should become a regular maintenance item.	Level 9	\$50.00
14	Relocate the mirrors to 40" maximum above the floor to the bottom of the reflective surface.	Level 10	\$100.00
15	Lower the hand sanitizer so the operable part is no higher than 48" above finished floor.	Level 9	\$50.00
16	Replace flush valves to the approach side.	Level 9	\$950.00
17	Relocate the break area to a location that provides the required clear floor space and turning radius or rearrange the room to achieve compliance.	Level 9	\$300.00
18	Remove and relocate furniture/break area.	Level 9	\$50.00

Grand Total	\$10,050.00
-------------	-------------

Summary Sheet for District 19 Field Office LaFollette

District 19 Field Office LaFollette

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Remove and replace the asphalt in the accessible parking spaces and access aisles to achieve slopes no greater than 1:48 (2%) in all directions.	Level 4	\$5,000.00
2	Install new van accessible signage.	Level 9	\$250.00
3	Modify thresholds to achieve a 1/2" high maximum change in level.	Level 3	\$3,500.00
4	Properly secure all floor mats to prevent slipping or curling.	Level 10	\$50.00
5	Re-arrange furniture to allow for a clear 36" width path.	Level 11	\$200.00
6	Alter or replace the reception desk with a compliant section that is 36" high and 36" wide. If the front edge of the desk protrudes, install side panels to protect eyes from being protruding objects.	Level 10	\$2,200.00
7	Replace the existing unit with a new dual height unit that will serve as an accessible unit and a unit for standing persons. Ensure compliance with 602 Drinking Fountains. Provide a drinking fountain apron for the higher fountain.	Level 10	\$3,000.00
8	Properly secure all floor mats to prevent slipping or curling.	Level 10	\$25.00
9	Replace the conference room table with a table that has the required knee	Level 11	\$500.00
10	Install compliant signage on the wall within 8" of the latch side of the door, between 48" and 60" from the finished floor.	Level 6	\$250.00
11	Alter or replace the door or Install an automatic door opening device.	Level 6	\$27,559.00
12	Adjust door closer mechanism. This should become a regular maintenance item.	Level 6	\$25.00
13	Lower the mirror so the bottom of the reflecting surface is 40" maximum above the finished floor.	Level 11	\$75.00
14	Provide protection at the exposed drains and water lines under the lavatory.	Level 6	\$100.00
15	Lower the hand sanitizer so the highest operable part is at or below 48 inches.	Level 11	\$75.00
16	Provide a 36 inches long minimum rear grab bar that extends from the centerline of the water closet 12 inches minimum on one side and 24 inches minimum on the other side.	Level 11	\$600.00
17	Remove stall partitions and possibly the urinal to provide required clear floor space for the water closet.	Level 6	\$2,500.00
18	Install compliant signage on the wall within 8" of the latch side of the door, between 48" and 60" from the finished floor.	Level 6	\$250.00
19	Adjust door closer mechanism. This should become a regular maintenance item.	Level 6	\$50.00
20	Install an automatic door opening device.	Level 4	\$1,870.00
21	Relocate boxes and vending machine outside of the restroom.	Level 4	\$250.00
22	Lower the mirror so the bottom of the reflecting surface is 40" maximum above the finished floor.	Level 11	\$75.00
23	Modify counter so it is a maximum of 34" above the finished floor.	Level 4	\$2,000.00

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
24	Provide protection at the exposed drains and water lines under the lavatory.	Level 6	\$100.00
25	Relocate water heater, boxes and supplies.	Level 5	\$50.00
26	Remove stall partitions to provide required clear floor space for the water closet.	Level 4	\$2,500.00
27	Provide a 36 inches long minimum rear grab bar that extends from the centerline of the water closet 12 inches minimum on one side and 24 inches minimum on the other side.	Level 11	\$600.00
28	Replace flush valve on the open side of the water closet or replace unit for compliance.	Level 6	\$1,750.00
29	Relocate the break area where the required maneuvering clearance is provided.	Level 8	\$4,000.00
30	It is recommended that the break area be relocated. Cost in Violation #29	Level 8	\$0.00

Grand Total	\$59,404.00
-------------	-------------

Summary Sheet for District 19 Field Office Harriman

District 19 Field Office Harriman

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Regrade parking space and access aisles to achieve slopes in all directions no greater than 1:48.	Level 8	\$3,000.00
2	Install compliant van accessible signage.	Level 6	\$250.00
3	Modify area in front of the doors to achieve a level landings in front of each door, and the proper maneuvering clearance for the doors.	Level 3	\$2,200.00
4	Relocate furniture to allow for a clear path of travel to the restroom.	Level 4	\$50.00
5	Replace the existing unit with a new dual height unit that will serve as an accessible unit and a unit for standing persons. Ensure compliance with 602 Drinking Fountains. Provide a drinking fountain apron for the higher fountain.	Level 10	\$3,000.00
6	Alter or replace the service desk with a compliant section that is 36" high and 36" wide.	Level 10	\$2,200.00
7	Install compliant signage on the wall within 8" of the latch side of the door, between 48" and 60" from the finished floor.	Level 6	\$250.00
8	Adjust door closer mechanism. This should become a regular maintenance item.	Level 6	\$50.00
9	Lower the mirror so the bottom of the reflecting surface is 40" maximum above	Level 11	\$75.00
10	Provide protection at the exposed drains and water lines under the lavatory.	Level 5	\$100.00
11	Re-mount grab bar so it is a maximum of 12" off the rear wall.	Level 10	\$50.00
12	Provide a new rear grab bar that is 36 inches long minimum and extend from the centerline of the water closet 12 inches minimum on one side and 24 inches minimum on the other side.	Level 10	\$600.00
13	Relocate toilet paper dispensers so it is mounted 7"-9" in front of the water closet.	Level 9	\$415.00
14	Install compliant signage on the wall within 8" of the latch side of the door, between 48" and 60" from the finished floor.	Level 6	\$250.00
15	Adjust door closer mechanism. This should become a regular maintenance item.	Level 6	\$50.00
16	Remove shelving to provide the required toe and knee clearance.	Level 6	\$50.00
17	Provide protection at the exposed drains and water lines under the lavatory.	Level 6	\$100.00
18	Modify sink to provide 34" maximum height with a 27" minimum knee clearance.	Level 6	\$2,000.00
19	Lower the mirror so the bottom of the reflecting surface is 40" maximum above the finished floor.	Level 11	\$75.00
20	Modify lavatory to provide the required clear floor space for the water closet.	Level 11	\$500.00
21	Provide a new rear grab bar that is 36 inches long minimum and extend from the centerline of the water closet 12 inches minimum on one side and 24 inches minimum on the other side.	Level 10	\$600.00

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
22	Re-mount grab bar so it is a maximum of 12" off the rear wall.	Level 10	\$50.00
23	Replace flush valve on the open/approach side of the water closet or replace unit for compliance.	Level 10	\$1,750.00
24	Replace table with one that provides the required knee clearance.	Level 4	\$50.00

Grand Total	\$17,715.00
-------------	-------------

Summary Sheet for District 19 Field Office Alcoa

District 19 Field Office Alcoa

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Stripe parking lot and designate a van accessible parking space with an access aisle and compliant signage.	Level 3	\$3,500.00
2	Remove and replace the path leading from parking to the building entrance.	Level 3	\$3,000.00
3	Modify the landing where it meets the asphalt drive lane to provide a level landing in front of door, and the proper maneuvering clearance for the door.	Level 3	\$1,500.00
4	Replace knob hardware with lever type hardware at main entry to the building.	Level 5	\$250.00
5	Modify threshold to achieve a 1/2" high maximum threshold.	Level 3	\$1,500.00
6	Replace knob hardware with lever type hardware.	Level 5	\$1,500.00
7	Replace the existing unit with a new dual height unit that will serve as an accessible unit and a unit for people who have trouble bending or stooping. Ensure compliance with 602 Drinking Fountains. Provide a drinking fountain apron for the higher fountain.	Level 10	\$3,650.00
8	Install compliant signage on the wall within 8" of the latch side of the door, between 48" and 60" from the finished floor.	Level 6	\$500.00
9	Install grab bars to comply with 609.	Level 6	\$750.00
10	Provide protection at the exposed drains and water lines under the lavatory.	Level 6	\$100.00
11	Lower the mirror so the bottom of the reflecting surface is 40" maximum above the finished floor.	Level 11	\$75.00
12	Install grab bars to comply with 609.	Level 4	\$750.00
13	Replace flush valve on the open side of the water closet or replace unit for compliance.	Level 6	\$1,750.00
14	Install a new, compliant, sink that is no higher than 34" and has the required knee clearance underneath. Ensure water pipes are properly protected from contact.	Level 11	\$1,800.00
15	When lavatory is replaced, ensure faucet control handles are lever style that do not require grasping and twisting to operate. Cost is included under violation #14.	Level 11	\$0.00
16	Lower the mirror so the bottom of the reflecting surface is 40" maximum above the finished floor.	Level 11	\$75.00

Grand Total	\$20,700.00
-------------	-------------

Summary Sheet for Region 1 Rest Area #12

Region 1 Rest Area #12

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Regrade the existing accessible parking spaces and access aisles to achieve a 1:48 (2.08%) max in all directions.	Level 3	\$6,500.00
2	Add another accessible parking space in the Truck/RV parking lot. Add parking signage.	Level 4	\$1,500.00
3	Add an access aisle that can serve both the existing and the new accessible parking space.	Level 5	\$600.00
4	Regrade the area to achieve slopes no greater than 2% in all directions.	Level 4	\$4,500.00
5	Add cross walk leading from access aisle to the median and from the median to the sidewalk.	Level 6	\$600.00
6	Remove and replace median to achieve cross slopes no greater than 1:48 and running slopes no greater than 1:20.	Level 3	\$8,000.00
7	Add cross walk leading from the pet walk area to the sidewalk.	Level 6	\$600.00
8	Replace 800sqft of concrete to achieve a running slope no greater than 1:20 (5%) or define it as a ramp and install handrails on both sides and level landing areas at the top and bottom.	Level 3	\$8,000.00
9	Replace concrete to achieve a running slope no greater than 1:20 (5%) or define	Level 3	\$7,500.00
10	Fill in the 1" gap in the expansion joint.	Level 3	\$200.00
11	Replace approximately 2,000sf of sidewalk from parking to the building, vending and picnic area.	Level 3	\$25,000.00
12	Remove and replace the curb ramp with a parallel curb ramp. Ensure the slope and cross slope are compliant and there is a level landing at the BOTTOM of the parallel ramp. The top of the curb ramp should be blended into a compliant path of travel into the vending area.	Level 4	\$500.00
13	Not having an accessible route from this parking to the building entrance is acceptable as long as signage is installed before the area where drivers need to choose where to park. It needs to clearly identify the route needed to get to the accessible truck/RV parking area. The picture sheet identifies the locations for the signage.	Level 4	\$500.00
14	Relocate the signage to the glass on the latch side of the door.	Level 8	\$100.00
15	Remove, replace or move the drinking fountains in a compliant location or add a skirt or apron or other barrier to ensure bottom leading edge of each fountain is at 27" aff.	Level 5	\$1,800.00
16	Lower the drinking fountains so the spout of the lower one is no higher than 36" and the spout of the higher one is between 38" and 43" above the finished floor.	Level 8	\$1,800.00
17	Lower brochure holder so the highest operable part is at 48" above finished floor.	Level 10	\$100.00
18	Secure mats to prevent slipping or curling.	Level 7	\$100.00
19	Adjust closers. This should be a regular maintenance item.	Level 11	\$100.00

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
20	Lower mirror 1" so the bottom of the reflecting surface is at or below 40" from the floor.	Level 11	\$100.00
21	Adjust closers. This should be a regular maintenance item.	Level 9	\$200.00
22	Convert an existing stall into an ambulatory stall.	Level 5	\$800.00
23	Provide at least one of each type of vending machine with operation mechanisms no higher than 48"aff. This may require some machines to be replaced.	Level 9	\$2,500.00

Grand Total	\$71,600.00
-------------	-------------

Summary Sheet for Region 1 Rest Area #13

Region 1 Rest Area #13

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Move or regrade accessible parking area to achieve no more than a 2% slope in all directions for both the accessible parking spaces and their access aisles.	Level 4	\$8,000.00
2	Install a 96" wide (8') minimum access aisle that directly serves the accessible truck/RV space.	Level 5	\$600.00
3	Move or regrade the accessible truck/RV parking area to achieve no more than a 2% slope in all directions for both the accessible parking space and the access aisle.	Level 4	\$3,000.00
4	Once a 96" wide (8') access aisle is added, add the required signage at the accessible truck/RV parking space and include that the space is "Van" accessible.	Level 6	\$500.00
5	Add a cross walk leading from the accessible parking area to the sidewalk leading to the pet walk area.	Level 7	\$500.00
6	Replace the concrete/asphalt walk leading to vending and picnic areas with a compliant surface that is firm, stable and slip resistant.	Level 5	\$15,000.00
7	Alter or replace the curb ramp to ensure a landing is provided and it meets the requirements of Section 406.4 (above).	Level 4	\$5,000.00
8	Alter or replace the ramp to ensure it is in full compliance with all applicable requirements of Section 405.	Level 5	\$25,000.00
9	Install new, compliant curb ramp.	Level 5	\$3,000.00
10	Add cross walk leading from the truck/RV parking to the curb ramp.	Level 7	\$600.00
11	Alter or replace the accessible route from the parking, on both sides, to the entry they serve. Ensure the running slope does not exceed 5% unless it meets all of the requirements of Section 405 and the cross slope does not exceed 2% anywhere along either route.	Level 5	\$45,000.00
12	Secure mats to the floor and ground to prevent slipping or curling.	Level 4	\$150.00
13	Relocate signage to the latch side of the door.	Level 9	\$100.00
14	Lower brochure holder so the highest operable part is at 48" above finished floor.	Level 11	\$250.00
15	Re-mount complaint drinking fountains in a location where they do not protrude into the path of travel or add a skirt or apron so the bottom is at 27" above finished floor. Relocate the comment box where it does not protrude into the path of travel.	Level 9	\$2,200.00
#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
16	Re-mount compliant drinking fountains in a location where they do not protrude into the path of travel or add a skirt or apron so the bottom is at 27" above finished floor. Relocate the comment box where it does not protrude into the path of travel.	Level 9	\$100.00

17	Install compliant signage on the wall on the latch side of the door at each restroom. Change the policy requiring people who need to use the family restroom to have to contact someone. This policy is discriminatory.	Level 5	\$650.00
18	Adjust door closers in each restroom. This should become a regular maintenance item.	Level 10	\$300.00
19	Lower the mirrors in each restroom to ensure the bottom of the reflecting surface does not exceed 40" above the floor.	Level 11	\$800.00
20	Install self-closing hinges in each accessible stall door and ensure there is a door pull on both sides. Lower the existing coat hook so it is no higher than 48" above finished floor. or add a second coat hook at the lower height.	Level 7	\$650.00
21	Upon remodeling of the Men's restroom, an ambulatory stall will need to be installed. This is not a 'retrofit' requirement but will be required when the restroom is otherwise altered. Until then it will be a low priority.	Level 11	\$1,800.00
22	Provide at least one of each type of vending machine with operation mechanisms no higher than 48" above finished floor. This may require some machines to be replaced.	Level 7	\$2,500.00

Grand Total	\$115,700.00
-------------	--------------

Summary Sheet for Region 1 Rest Area #16

Region 1 Rest Area #16

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Install a 96" wide (8') minimum access aisle that directly serves the accessible truck/RV space.	Level 4	\$1,200.00
2	Replace 1,400sqft of sidewalk from parking to the vending building and picnic areas.	Level 3	\$14,000.00
3	Price is included in Violation #1 above.	Level 3	\$0.00
4	Install new, compliant curb ramp and landing.	Level 5	\$3,000.00
5	Add edge protection.	Level 4	\$1,000.00
6	Secure mats.	Level 4	\$25.00
7	Relocate signage to the latch side of the door.	Level 6	\$25.00
8	Lower brochure holder so the highest operable part is at 48"above finished floor..	Level 11	\$100.00
9	Replace the "Lo" fountain & add a skirt or apron to the "Hi" fountain so the bottom is at 27"above finished floor..	Level 5	\$2,000.00
10	Secure mats.	Level 4	\$25.00
11	Install compliant signage on latch side of the door.	Level 6	\$100.00
12	Adjust closer.	Level 4	\$300.00
13	Lower mirror.	Level 6	\$100.00
14	Lower dispensers.	Level 7	\$200.00
15	Adjust closers.	Level 4	\$600.00
16	Lower dispensers.	Level 7	\$400.00
17	Convert an existing stall into an ambulatory stall.	Level 4	\$300.00
18	Provide at least one of each type of vending machine with operation mechanisms no higher than 48"above finished floor.	Level 9	\$2,500.00

Grand Total	\$25,875.00
-------------	-------------

Summary Sheet for Region 1 Rest Area #17

Region 1 Rest Area #17

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Alter or move the accessible parking space to achieve a slope no greater than 2% in all directions.	Level 4	\$3,500.00
2	Ensure each parking space has it's own sign that is mounted 60" to the bottom most character. Van accessible parking spaces need to have additional "van" signs.	Level 4	\$600.00
3	Install a 96" wide (8') minimum access aisle that directly serves the accessible truck/RV space.	Level 4	\$600.00
4	Once a 96" wide (8') access aisle is added, add the required signage at the accessible truck/RV parking space and include that the space is "Van" accessible.	Level 6	\$500.00
5	Add a cross walk leading from the pet walk area to the sidewalk.	Level 7	\$500.00
6	Add a cross walk between the truck/RV parking and the curb ramp leading to the building entrance.	Level 7	\$300.00
7	Alter or replace concrete landing at the curb ramp to achieve a level landing. Alter or replace approximately 140 feet of concrete sidewalk to either bring the slope at or below 5% or add level landing areas every 30' and at the change of direction areas. Handrails will need to be installed if slope exceeds 5%.	Level 5	\$10,000.00
8	Alter or replace concrete landing at the curb ramp to achieve a level landing. Alter or replace approximately 2100 feet of concrete sidewalk to bring the cross slope at or below 2%. Handrails will need to be installed where running slope exceeds 5%.	Level 2	\$25,000.00
9	Remove and replace sidewalk leading from parking to the main building to achieve a running slope no greater than 5% and a cross slope no greater than 2%.	Level 3	\$60,000.00
10	Lower fountains so they are at 27" aff from the ground to the bottom of the fountains.	Level 7	\$1,200.00
11	Secure mats to the floor to prevent slipping or curling.	Level 4	\$50.00
12	Alter the door for compliance or install power door openers at each door.	Level 8	\$4,200.00
13	Adjust the door closer. This should become a regualr maintenance item.	Level 6	\$200.00
14	Raise toilet paper dispenser.	Level 5	\$300.00
15	Install flush control on the open side of the water closet.	Level 7	\$1,500.00
16	Install self-closing hinges and lower the coat hook so it is no higher than 48" above finished floor.	Level 7	\$450.00
17	Alter the stall configuration to ensure at least one fully compliant ambulatory stall is provided.	Level 7	\$3,000.00
18	Provide at least one of each type of vending machine with operation mechanisms no higher than 48" above finished floor.	Level 12	\$2,500.00

Grand Total	\$114,400.00
-------------	--------------

Summary Sheet for Region 1 Rest Area #18

Region 1 Rest Area #18

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Watch this area for heaving soil. Currently the Consultant team considers this within a reasonable tolerance for an existing condition, but it should be watched. It's being given a low priority but costs for resolution are provided.	Level 10	\$3,000.00
2	Restripe the parking lot to add an access aisle. Ensure the access aisle added connects to an accessible route.	Level 4	\$750.00
3	Provide accessible signage, the accessible parking sign at 60" above finished floor minimum high to the bottom of the sign.	Level 6	\$200.00
4	Replace 400 feet of sidewalk in these areas to achieve a running slope no greater than 5% and a cross slope no greater than 2%.	Level 2	\$4,000.00
5	Add cross walk leading from the pet walk area to the sidewalk.	Level 7	\$500.00
6	Add cross walk leading from truck parking to the curb ramp.	Level 7	\$500.00
7	Alter or replace the curb ramp and ensure there is a level landing at the top.	Level 4	\$6,000.00
8	Remove and replace sidewalk leading from parking to the main building to achieve a running slope no greater than 5% and a cross slope no greater than 2%.	Level 3	\$60,000.00
9	Adjust door closer mechanism. This should become a regular maintenance item.	Level 4	\$50.00
10	Properly secure the mats to the floor to prevent slipping or curling.	Level 4	\$50.00
11	Alter and/or move the drinking fountain where it will not be a protrusion and the clear floor space can be met.	Level 7	\$3,600.00
12	Alter doors to ensure a full 18" is provided on the pull side or Install power assisted door openers.	Level 8	\$4,800.00
13	Raise toilet paper dispenser so it is at 12" above finished floor. Raise toilet paper dispenser so it's a minimum of 12" above the grab bar and a maximum of 48". the bottom of the dispenser from the grab bar.	Level 5	\$300.00
14	Adjust grab bar so it is mounted in compliance with the standards.	Level 8	\$250.00
15	Replace flush valve to approach side.	Level 5	\$2,200.00
16	Lower the coat hook to at or below 48" from the floor, or add a second on that is at or below 48", and install self-closing hinges.	Level 7	\$250.00
17	Alter stall design to ensure at least one stall in both the Men's and Women's restrooms are fully compliant ambulatory stalls.	Level 4	\$4,400.00
18	Where forward and side reaches are unobstructed, the high reach shall be 48 inches maximum and the low reach shall be 15 inches minimum above the finish floor. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	Level 8	\$6,000.00

Grand Total	\$96,850.00
-------------	-------------

Summary Sheet for Welcome Center 25

Welcome Center 25

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Add two accessible parking spaces (one being van accessible) with access aisles and compliant signage.	Level 3	\$2,200.00
2	Add complaint curb ramp leading from the new access aisle to the sidewalk for access.	Level 3	\$3,000.00
3	Add accessible signage ensuring each parking space has it's own sign on the one on the left (looking at the building) has 'van' accessible signage.	Level 6	\$650.00
4	Move the accessible parking spaces so they are on the closest accessible route to the building. Ensure at least one of the accessible space is designated as van accessible. Ensure both are served by an access aisle and compliant signage is provided.	Level 3	\$3,000.00
5	Ensure slopes in parking spaces and access aisle are no greater than 2% in all directions and add accessible parking signage.	Level 3	\$3,000.00
6	Add an access aisle to serve the existing accessible parking space.	Level 4	\$2,500.00
7	Stripe a cross walk leading from the access aisle to the accessible entrance. Ensure the slope of the path from the building to the parking has a running slope no greater than 5% and a cross slope on greater than 2%.	Level 3	\$1,500.00
8	Add signage indicating the reserved space is an accessible parking space.	Level 6	\$450.00
9	Remove and regrade sidewalk to achieve a running slope no greater than 5% or	Level 3	\$7,500.00
10	Remove and replace the curb ramp to achieve a running slope no greater than 8%.	Level 3	\$4,500.00
11	Ensure bridge and path to the picnic tables have compliant slopes as indicated in General Notes above.	Level 7	\$7,500.00
12	Ensure each building that is open to the public has at least one clearly identified accessible entrance.	Level 5	\$8,500.00
13	Adjust the door closer. This should become a regular maintenance item.	Level 4	\$100.00
14	Secure the mat to prevent slipping or curling.	Level 4	\$100.00
15	Add directional signage.	Level 6	\$400.00
16	Request vending machines where operable parts are no higher than 48" above the finished floor.	Level 12	\$2,500.00
17	Make necessary adjustments to achieve a compliant portion of the reception desk.	Level 4	\$3,400.00
18	Relocate the comment box to a compliant height/location.	Level 6	\$50.00
19	Install compliant signage on the latch side of the door.	Level 6	\$250.00
20	Install lever door hardware.	Level 5	\$600.00
21	Raise the fountain.	Level 5	\$3,250.00
22	Raise the toilet paper dispenser so it is a minimum of 12" to the bottom of the dispenser if above the grab bar, or lower it so it's at least 1 1/2" below the grab bar.	Level 6	\$600.00

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
23	Alter or replace toilet so the flush control is on the open side of the water closet.	Level 5	\$2,200.00
24	Alter the plumbing so that the flush control is below the required location for the grab bar and then reinstall the grab bars in the proper location. Alternatively, install an auto-flush mechanism ensuring the manual flush element is on the wide side of the water closet.	Level 5	\$3,500.00
25	Install a self-closing hinge and ensure a door handle is on both sides of the accessible stall door.	Level 7	\$500.00
26	Lower the coat hook or install a second coat hook within accessible reach ranges.	Level 10	\$400.00

Grand Total	\$62,150.00
-------------	-------------

Summary Sheet for Region 1 Welcome Center #30

Region 1 Welcome Center #30

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Add an access aisle.	Level 9	\$500.00
2	Alter the accessible parking space in the truck/RV lot to ensure it has no more than 2% slope in any direction, no level changes and an access aisle complying with the requirements.	Level 4	\$3,800.00
3	Add one accessible parking space that is van accessible with an access aisle across the parking lot where the path of travel does not have to cross the street. Add a van accessible parking sign to serve the space.	Level 4	\$2,200.00
4	Remove and replace sidewalk to achieve a 2% cross slope.	Level 8	\$4,500.00
5	Remove and replace sidewalk to achieve a 2% cross slope.	Level 8	\$3,300.00
6	This is currently within the acceptable tolerances published by the US Access Board and no action is necessary. However, it should be on a 'watch' list to ensure it does not become more egregious as soils shift.	Level 11	\$3,500.00
7	Remove and replace sidewalk to achieve a 2% cross slope.	Level 4	\$6,500.00
8	Remove and replace landing to achieve a slope no greater than 1:48.	Level 8	\$2,800.00
9	Remove and replace landing to achieve a slope no greater than 1:48.	Level 8	\$2,800.00
10	Ramp the area onto the grass where pets are allowed to go to provide a compliant path of travel.	Level 4	\$1,800.00
11	Secure mat to prevent slipping or curling.	Level 4	\$100.00
12	Check all interior doors and make necessary adjustments so all doors require no more than 5lbs of pressure to operate.	Level 10	\$100.00
13	Adjust door closer to ensure the opening force is no more than 5lbs. This should become a regular maintenance item.	Level 6	\$100.00
14	Replace flush valve to approach side.	Level 5	\$1,300.00
15	Lower hand dryer.	Level 9	\$250.00
16	Install an offset flange so the center line of the water is between 16" and 18" in the "side A" restroom.	Level 7	\$2,000.00
17	Install a self-closing hinge on the doors to both the accessible and ambulatory stalls in all restrooms.	Level 6	\$1,200.00
18	Lower the towel dispenser to ensure the highest operable part is at or below 48".	Level 11	\$150.00
19	Relocate the table outside of the breakroom to provide the necessary clear floor space.	Level 4	\$100.00
20	Install a new, fully compliant sink.	Level 10	\$3,600.00

Grand Total	\$40,600.00
-------------	-------------

Summary Sheet for Region 1 Welcome Center #31

Region 1 Welcome Center #31

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Raise the accessible parking space signage and ensure signage is 60 inches minimum above the ground surface measured to the bottom of the sign	Level 6	\$650.00
2	Install accessible parking space signage.	Level 6	\$450.00
3	Rework curb ramp to ensure compliance.	Level 4	\$3,000.00
4	Provide a compliant accessible route to the current pet area including a curb ramp and all required pedestrian elements.	Level 4	\$1,000.00
5	Remove and replace curb ramp and ensure flares do not exceed 10%	Level 4	\$4,000.00
6	Modify or replace sidewalk to achieve a running slope of 5% or less and a cross slope of 1:48 (2%) maximum.	Level 4	\$52,000.00
7	Stripe a cross walk to sidewalk that leads to welcome center and accessible route.	Level 5	\$1,000.00
8	Remove and replace curb ramp and ensure flares do not exceed 10%	Level 4	\$4,000.00
9	Rework curb ramp to ensure compliance.	Level 4	\$3,000.00
10	Adjust door closing mechanisms. This should become a regular maintenance item.	Level 6	\$100.00
11	Secure the mat to prevent slipping or curling.	Level 4	\$200.00
12	Provide a 30 X 48 inch minimum clear floor space centered on drinking fountain	Level 6	\$3,000.00
13	Add self-closing hinge to compartment doors.	Level 6	\$400.00
14	Provide at least 1 picnic table in each area that complies with 902.2 and 902.3.	Level 6	\$4,000.00

Grand Total	\$76,800.00
-------------	-------------

Summary Sheet for Welcome Center #33

Welcome Center #33

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Secure mats to prevent slipping or curling.	Level 5	\$100.00
2	Relocate the comment box to a compliant height/location that is out of the main circulation path.	Level 10	\$50.00
3	Move the drinking fountains so that the centerline of the accessible (lower) drinking fountain is a minimum of 15" from the alcove wall. Centering it in the alcove or reversing the hi and low fountains is also an option.	Level 4	\$3,250.00
4	Relocate the signage to the wall next to the latch side of the door. Make sure it's no more than 8" from the door frame, between 15" and 48" from the floor and has the required raised texture and Braille.	Level 5	\$250.00
5	Adjust closer to less than 5 lbs. of pressure. This should be a regular maintenance item.	Level 4	\$100.00
6	Move the water closet or the wall so the centerline is between 16" and 18" from the side wall. Another option might be to install an offset flange.	Level 7	\$1,150.00
7	Lower mirrors so the bottom of the reflective surface is a maximum of 40" above the floor.	Level 8	\$300.00
8	Lower urinals on each side so there is at least one at or below 17" to the rim.	Level 7	\$1,350.00
9	Lower the coat hook in each accessible stall or add an additional coat hook at	Level 9	\$250.00
10	Install self-closing hinges on all accessible stall doors.	Level 7	\$500.00

Grand Total	\$7,300.00
-------------	------------